

PCS Part # 29470 - Potential Gasket Issue

29470


- ☐ SUBARU
 - ☒ B9 TRIBECA
 - ☒ BAJA
 - ☒ FORESTER
 - ☒ IMPREZA
 - ☒ LEGACY
 - ☒ OUTBACK
 - ☒ SVX
 - ☒ TRIBECA

29470


O.E. Type Thermostat



This unit is currently shipped from the factory with gasket attached. Certain applications require replacment of this gasket with PCS gasket # 99182



Installed On 29470



Alternative Gasket For 29470